

**FRONTIER
MEDICAL SCREENS
BS 5852 IGNITION SOURCE 7
CERTIFICATE**



Early
Learning
Furniture

01733 511121

sales@earlylearningfurniture.co.uk

FLAMMABILITY TEST CERTIFICATE – 79086

COMPANY DETAILS: CAMIRA FABRICS
MELTHAM MILLS, MELTHAM, WEST YORKSHIRE
HD9 4AY, UK

CONTACT NAME(S): LUKE RUSSELL
TEL: 01924 481368
EMAIL: luke.russell@camirafabrics.com

DATE RECEIVED: 28/11/2017
DATE TESTED: 04/12/2017
DATE ISSUED: 05/12/2017
PO NUMBER: 83A06702

SAMPLE DESCRIPTION: VITA WITH INTER FLAM. (TESTED WITH INTERLINER PROVIDED BY THE CUSTOMER)
COLOUR: SEAL
QUALITY/BATCH REF: 436918
MODLE REF: NOT STATED
COMPOSITION: NOT STATED
SAMPLE END USE: NOT STATED
MANUFACTURER: NOT STATED
SUPPLIER/BUYER: NOT STATED

TEST METHOD(S):
BS 5852:2006 Clause 11 – Method of test for the ignitibility of upholstered composites ignition source 7.

PRE-TREATMENT:
Water Soak procedure in accordance with Annex E of BS 5852:2006.

CONDITIONING:
The sample was conditioned for 72 hrs in ambient conditions for at least 24 hrs in a specified atmosphere at $23 \pm 2^{\circ}\text{C}$ and $50 \pm 5\%$ r h.

Authorised By:



Zeb Alam
Operations Director

Mark Jones
Quality Manager

Karen Brooks
Managing Director

FLAMMABILITY TEST CERTIFICATE – 79086

TEST RESULTS:

“The Following test results relate only to the ignitibility of the combination of the materials under the particular conditions of test; they are not intended as a means of assessing the full potential fire hazard of the materials in use.”

TEST RESULTS:

TEST CRITERIA – BS 5852:2006 Source 7	INITIAL TEST	REPEAT TEST
Flaming Ceased:	09.08	08.36
PROGRESSIVE SMOULDERING CRITERIA (4.1)		
FILLING MATERIAL USED:	CMHR 35	CMHR 35
b) Detectable amounts of smoke, heat or glowing 60 mins after crib ignition?	NO	NO
c) Displays unsafe escalating combustion, requires to be forcibly extinguished?	NO	NO
d) Smouldering consumed the test specimen within the duration of the test?	NO	NO
e) Smoulder to the extremities i.e. upper or lower margins, either side or to its full thickness?	NO	NO
f) On final inspection, any evidence of charring more than 100 mm in any direction (apart from upwards) from the original nearest position?	NO	NO
FLAMING CRITERIA (4.2)		
b) Flaming continued for more than 13 minutes after the ignition of the crib?	NO	NO
c) Displays unsafe escalating combustion, requires to be forcibly extinguished?	NO	NO
d) Flaming and/or smouldering consumed the test specimen within the duration of the test?	NO	NO
e) Flame front reaches the lower margin, either side or passes through the full thickness?	NO	NO
TEST RESULTS	PASS	PASS

CONCLUSION:

The sample supplied **meets** the test criteria of BS 5852:2006 Clause 11, Source 7.

END OF REPORT